

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-013792**Date Inspected:** 16-Apr-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, M.Manikandan was present during the time noted above for observations relative to the work being performed.

**OBG # TRIAL ASSEMBLY YARD**

This QA inspector performed dimensional check on floor beam using 1.5M straight edge to check flatness for below segment. Reports forwarded to team leader for further action

7CW-PP53, PP 54 and PP55

7DW-PP56, PP57 and PP58

7EW-PP59 and PP60

This QA Inspector randomly observed the following work in progress:

**OBG # TRIAL ASSEMBLY YARD (7BW-7CW)****SMAW Process:**

Welding of weld joint – 008 located on PCMK OBW7B, Deck panel transverse splice weld joining 7BW and 7CW. Welder is identified as 045246. Welding was been performed against critical welding repair report B-CWR1408. ZPMC CWI is identified as Li Yang. The welding variables recorded by QC appeared to comply

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

with the WPS-345-SMAW-1G (1F)-FCM-Repair-1.

OBG # TRIAL ASSEMBLY YARD (7BW-7CW)

SMAW Process:

Welding of weld joint – 010 located on PCMK OBW7, Edge panel transverse splice weld joining 7BW and 7CW at crossbeam side. Welder is identified as 047864. Welding was been performed against critical welding repair report B-CWR1408. ZPMC CWI is identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-3G (3F)-FCM-Repair-1.

OBG # TRIAL ASSEMBLY YARD (7BW-7CW)

SMAW Process:

Welding of weld joint – 009 located on PCMK OBW7B, Side panel transverse splice weld joining 7BW and 7CW at crossbeam side. Welder is identified as 045196. Welding was been performed against critical welding repair report B-CWR1408. ZPMC CWI is identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-345-SMAW-4G (4F)-FCM-Repair-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### Summary of Conversations:

No Relevant Conversation.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact , who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Manikandan,Murugan	Quality Assurance Inspector
<b>Reviewed By:</b>	Carreon,Albert	QA Reviewer

---